

**RESPONSE TO ASH POND OBSERVATIONS AND RECOMMENDATIONS PER  
AECOM'S WEST ASH POND VISUAL SITE INSPECTION REPORT - 2019**

**Documented to meet 257.83(b)(5)**

	<b>DEFICIENCY/OBSERVATION (inspection recommendation #)</b>	<b>CORRECTIVE MEASURE</b>
1	Exterior Slope - A few small trees, bushes, and brush have grown on the embankment slope.	Small trees/shrubs have been cut down. Vegetation was sprayed.
2	Exterior Slope - Concrete stairs leading to the Ohio River are dilapidated. Unstable terrain underlies collapsing stairs.	Lower, damaged stairs were removed. Remaining stairs will be removed as part of the current pond closure project.
3	Exterior slope - Small animal burrows were observed on top of the embankment slope.	Due to ongoing construction activities, these observations are being addressed as the embankment is modified during the current the pond closure project.